



## OPTION 2 – Stream Floor Maintenance

---

- Remove all trees, bushes, & cattails from stream floor
- Trim back slope vegetation that extends over stream floor

Estimated flood protection provided: Accommodate 25–50 year rainfall event without flooding